

2000 MP Index

A Guide to MP Volume 39

2000 Subject Index

This is an alphabetical list of primary topics included in Volume 39 of *MP* Subject classifications are followed by issue number, then page number. An alphabetized list of authors appears on p. 82.

ACIDS

- Anodic Protection in the Sulfuric Acid Industry, 12-22
- Liquid Scavengers—Their Effectiveness and Compatibility with Downstream Processes, 12-54

ALUMINUM AND ALLOYS

- Thermal Spray Applications for Power Plant Components, 3-60

ANODES

See also CATHODIC PROTECTION

- Anodic Protection in the Sulfuric Acid Industry, 12-22
- A Practical Case: Cathodic Protection: Conventional Shallow Groundbed vs Deep Groundbed Anodes, 10-22
- Case Study: CP Retrofits of Onshore Facilities, 2-34
- Galvanic Protection of an Offshore Loading Pipeline in the Baltic Sea, 5-24
- Interference Evaluation Between Manifold and Wet Christmas Tree CP Systems, 5-28
- Phorgotten Phenomena: Using Impressed Current Cathodic Protection in Urban Areas, 4-30
- Special Report: CP Corrosion Control of Municipal Infrastructure, 2-26
- Zinc Mesh Cathodic Protection Systems, 8-28

BACTERIA

See MICROBIAL ATTACK

- Microbiologically Influenced Corrosion Monitoring: Real World Failures and How to Avoid Them, 1-54

BOILERS

- Failure Analysis: Corrosion-Fatigue and Graphitization Cause Boiler Steam Tube Failure, 8-82
- Special Report: Refinery Boiler Feedwater Systems: Corrosion and Control, 6-46
- Steam Surface Condenser Tubes: Watch Out for Sneaky Corrosion, 5-60

CATHODIC PROTECTION

See also ANODES

- Anodic Protection in the Sulfuric Acid Industry, 12-22
- A Practical Case: Cathodic Protection: Conventional Shallow Groundbed vs Deep Groundbed Anodes, 10-22
- A Titanic Preservation Project, 3-26
- Case History: Long-Term Evaluation of CP for Interlocking Sheet Pile Bulkheads, 3-38
- Case Study: CP Retrofits of Onshore Facilities, 2-34
- Cathodic Protection Criteria and Its Application to Mature Pipelines, 4-26
- Cathodic Protection in Discontinuous Electrolytes, 9-32

- Consideration of IR Drops in 'On' Potential CP Criteria, 7-26
- Corrosion Inside Casing—A Field Case History, 12-28
- Corrosion Simulation Software Predicts Interaction of Underground Electric Fields, 1-28
- Detection and Assessment of Alternating Current Corrosion, 3-34
- The Effectiveness of External Corrosion Control in Lake Maracaibo, 12-34
- Galvanic Protection of an Offshore Loading Pipeline in the Baltic Sea, 5-24
- Interference Evaluation Between Manifold and Wet Christmas Tree CP Systems, 5-28
- Phorgotten Phenomena: Cathodic Shielding Can Be a Major Problem After a Coating Fails, 4-44
- Phorgotten Phenomena: The Strange Case of the Intermittent Condition, 3-42
- Phorgotten Phenomena: The Strange Case of the Disappearing/Reappearing Insulators, 7-32
- Phorgotten Phenomena: Using Impressed Current Cathodic Protection in Urban Areas, 4-30
- Potential Measurement Interpretation on Isolating Joints, 9-26
- Recent Advances in Offshore Cathodic Protection Monitoring, 6-24
- Special Report: CP Corrosion Control of Municipal Infrastructure, 2-26
- Zinc Mesh Cathodic Protection Systems, 8-28

CHEMICAL TREATMENT

- Control of Water Treatment Programs in Buildings: Owner and Chemical Vendor Responsibilities, 7-52
- Corrosion Inhibitor Selection for Arctic and Subsea High-Velocity Flowlines, 3-70
- Current Water Treatment Practices—Utility and Industrial Steam Systems, 10-48
- Effective Water Treatment of Building HVAC Systems, 9-58
- Effect of Cooling Water Impurities on Deposit Control Polymer Performance, 5-54
- Evaluation of Environmentally Friendly Corrosion Inhibitors for Sour Service, 8-62
- Heat Exchanger Design & Operation to Minimize Efficiency Loss, 6-52
- Laboratory Methodologies for Corrosion Inhibitor Selection, 8-58
- Liquid Scavengers—Their Effectiveness and Compatibility with Downstream Processes, 12-54
- Microbiologically Influenced Corrosion Monitoring: Real World Failures and How to Avoid Them, 1-54
- New Bactericide for Biocide-Resistant

- Sulfate-Reducing Bacteria, 4-52
- Nitrogen Sparging and Blanketing of Water Storage Tanks, 4-56
- Online Control of Coordinated Phosphate Programs in High-Pressure Steam Generators, 3-76
- Reduction of Dissolved Oxygen in Water: Hydrazine and Its Organic Substitutes, 7-58
- Repassivation of 13% Cr Steel Dependent on Brine pH, 2-64
- Special Report: Refinery Boiler Feedwater Systems: Corrosion and Control, 6-46
- Steam Surface Condenser Tubes: Watch Out for Sneaky Corrosion, 5-60
- Why Chemically Clean Thermal Fluid Systems?, 9-64

COATINGS

- Advances in Field Joint Coatings for Underground Pipelines, 8-40
- A User's Practical Guide to Alkyd Coatings, 10-32
- Book Review: Corrosion Prevention by Protective Coatings, 3-56
- Coatings for Aboveground Steel in Coal-Fired Plants, 10-36
- Connector Technologies for Joining Lined Pipeline Segments, 9-48
- Corrosion Inside Casing—A Field Case History, 12-28
- The Effectiveness of External Corrosion Control in Lake Maracaibo, 12-34
- The Effect of Coupling Agents on the Anti-Corrosion Properties of Acrylic Latex Coatings, 9-42
- Evaluating Pipeline 'Tape' Coatings—How Do They Compare? 1-43
- Failure Avoidance: Blistering of Epoxy Lining in Potable Water Tank, 12-44
- Failure Avoidance: What You Can't See... *Can Hurt You*, 5-44
- Fast-Cure AHC Epoxy Coatings for Tank and Pipe Applications, 6-32
- Inorganic Zinc Coatings—Well Known, Yet Commonly Forgotten Facts, 5-38
- In-Situ Corrosion Sensor for Coating Testing and Screening, 2-46
- Inspection and Interpretation Using NACE No. 5/SSPC-SP 12, 4-38
- Maintenance Painting/Practical Advice, 10-39
- Paints and Coatings—New Trends Respond to Environmental Concerns, 9-22
- Phorgotten Phenomena: Coating of Faying Surfaces, 7-45
- Phorgotten Phenomena: Cathodic Shielding Can Be a Major Problem After a Coating Fails, 4-44
- Phorgotten Phenomena: Condenser Tube Erosion-Corrosion Repairs Using Coatings, 2-52
- Phorgotten Phenomena: Maximizing IOZ's

2000 MP Index

A Guide to MP Volume 39 2000 Subject Index

Effectiveness with a Three-Coat System, 5-42

Phorgotten Phenomena: Measuring Each Coat Thickness in a Multi-Coat System by Averaging Using SSPC-PA 2, 3-54

Phorgotten Phenomena: Soluble Salt Reactions are Visible with Time, 4-42

Sealer Coatings for Thermal Spray Aluminum in the Offshore Industry, 1-46

Selecting Internal Coatings for Sweet Oil Well Tubing Service, 2-54

Selecting Liquid Coatings for Pipeline Repair and Rehabilitation, 8-46

Sources of Bubbles, Foam, and Voids in Coatings, 3-50

Special Report: Coating Inspection: What Has Changed?, 7-40

Summary Report: Fusion-Bonded Epoxy Coatings for Underground Pipelines, 6-38

Thermal Spray Applications for Power Plant Components, 3-60

CONCRETE

Carbonation and Its Effects in Reinforced Concrete, 1-64

Permanent Corrosion Monitoring in New and Existing Reinforced Concrete Structures, 7-66

FEATURE ARTICLES (VARIOUS SUBJECTS)

1999 U.S. Corrosion Career Survey, 1-16

A Titanic Preservation Project, 3-26

Alpine Pipeline Brings Technology 'First' to Alaska's North Slope, 2-16

Complying with the OQ Rule, 2-23

CORROSION/2000 Plenary Lecture: The Pipeline OQ Rule—Perspectives, Options, and Implementation, 4-18

CORROSION/2000 Recap, 6-77

Corrosion Control: The Next Decade, 1-22

The Cost of Maintaining an Aging Water Infrastructure, 6-20

The Golden Dollar: Testing and Protection of the New U.S. Coin, 5-20

Improving Aging Airplane Safety, 3-20

Introducing MP's 2000 Editorial Advisory Board, 3-30

Management of the U.S. Pipeline Safety Program, 7-20

MP Names New Technical Editor, 9-20

Motor Speedway Bridge Collapse Caused by Corrosion, 7-18

NACE Roundtable: Future of Corrosion Control in the Pipeline Industry, 12-16

Northstar Pipeline Designed for Safety in Alaska's Arctic Ocean, 8-20

Paints and Coatings—New Trends Respond to Environmental Concerns, 9-22

GALVANIC CORROSION

Failure Avoidance: Galvanic Effects in Carbon Bed Adsorbers, 7-77

Galvanic Protection of an Offshore Loading Pipeline in the Baltic Sea, 5-24

Phorgotten Phenomena: Autogalvanic Corrosion, 3-92

GAS OIL AND GAS PRODUCTION

HEAT EXCHANGERS

See also BOILERS; POWER PLANTS

Case History: Corrosion Failure of Duplex Stainless Steel Equipment in a PVC Plant, 5-76

Heat Exchanger Design & Operation to Minimize Efficiency Loss, 6-52

Phorgotten Phenomena: Condenser Tube Erosion-Corrosion Repairs Using Coatings, 2-52

Phorgotten Phenomena: Condenser Tube Repairs Using Tube Inserts, 5-74

INHIBITORS

See CHEMICAL TREATMENT

INSPECTION

An Improved Corrosion Inspection and Monitoring Instrument for Used Oil Well Tubing, 2-72

In-Situ Corrosion Sensor for Coating Testing and Screening, 2-46

Inspection and Interpretation Using NACE No. 5/SSPC-SP 12, 4-38

Special Report: Coating Inspection: What Has Changed?, 7-40

LININGS

Connector Technologies for Joining Lined Pipeline Segments, 9-48

Corrosion Inside Casing—A Field Case History, 12-28

Fluoropolymer Lining Systems: An Economical Alternative, 1-38

LOCALIZED ATTACK

See also MICROBIAL ATTACK

Case History: Corrosion Failure of Duplex Stainless Steel Equipment in a PVC Plant, 5-76

Case History: Quantitative Damage Evaluation of Localized Deep Pitting, 4-78

Cavitation Corrosion in a Continuous Catalytic Reformer Unit, 6-62

Comparison of Pitting Corrosion Rates of Coupons and Pipes, 10-58

Corrosion of API 5L B and X52 in Crude Oil/Water/Gas Mixtures, 2-76

Pitting Corrosion on Weld Joints of Offshore Structure Jackets, 4-70

MARINE ENVIRONMENTS

See OFFSHORE STRUCTURES; SEAWATER

MATERIALS SELECTION & DESIGN

An Improved Corrosion Inspection and Monitoring Instrument for Used Oil Well Tubing, 2-72

ASTM A 312—Quality? Who Bears the Burden? 5-70

Carbonation and Its Effects in Reinforced Concrete, 1-64

Case History: 20th Century Failure: Popped Rivets, 1-68

Case History: Ambient Temperature SCC of Stainless Steel High-Pressure Hose Connectors, 3-96

Case History: Corrosion Failure of Duplex Stainless Steel Equipment in a PVC Plant, 5-76

Case History: Grooving Failure of Tall Oil Evaporator, 12-70

Case History: Quantitative Damage Evaluation of Localized Deep Pitting, 4-78

Cavitation Corrosion in a Continuous Catalytic Reformer Unit, 6-62

Comparison of Pitting Corrosion Rates of Coupons and Pipes, 10-58

Corrosion Detection System for Thermally Insulated Pipeline Buried in Soil, 7-72

Corrosion of API 5L B and X52 in Crude Oil/Water/Gas Mixtures, 2-76

Corrosion Quantification Test for Flanges with Graphite-Based Gaskets, 4-64

Determining PREN for High-Chromium Cast Irons, 8-78

Erosion-Corrosion Degradation of Two Engineering Materials, 12-64

Failure Analysis: Corrosion-Fatigue and Graphitization Cause Boiler Steam Tube Failure, 8-82

Failure Avoidance: Galvanic Effects in Carbon Bed Adsorbers, 7-77

Failure Avoidance: Handle Titanium in Chlorine Environment with Care, 10-62

Failure Avoidance: MIC Causes Pipe Weld Joint Problems, 6-68

Intelligent Sensors for the Oil and Gas Industry, 8-74

Permanent Corrosion Monitoring in New and Existing Reinforced Concrete Structures, 7-66

Phorgotten Phenomena: Autogalvanic Corrosion, 3-92

Phorgotten Phenomena: Condenser Tube Repairs Using Tube Inserts, 5-74

Pitting Corrosion on Weld Joints of Offshore Structure Jackets, 4-70

Preleak Detection Systems for Dual Laminate Equipment—A User's Perspective, 9-84

Special Report: Caustic Injection Revisited—An Old Method for Controlling Crude Tower Overhead Corrosion, 8-70

Special Report: Chloride SCC of Stainless Steel? No—Cyclic Strain Cracking!, 9-78

Special Report: SOHIC Without H₂S, 3-86

Technical Note: Comparison of American and Russian Commercially Pure Titanium, 4-74

MICROBIAL ATTACK

See also LOCALIZED ATTACK

Failure Avoidance: MIC Causes Pipe Weld Joint Problems, 6-68

Microbiologically Influenced Corrosion Monitoring: Real World Failures and How to Avoid Them, 1-54

New Bactericide for Biocide-Resistant Sulfate-Reducing Bacteria, 4-52

2000 MP Index

A Guide to MP Volume 39 2000 Subject Index

NATURAL GAS

See **OIL AND GAS PRODUCTION**

OFFSHORE STRUCTURES

See also **SEAWATER**

Case History: Long-Term Evaluation of CP for Interlocking Sheet Pile Bulkheads, 3-38

The Effectiveness of External Corrosion Control in Lake Maracaibo, 12-34

Galvanic Protection of an Offshore Loading Pipeline in the Baltic Sea, 5-24

Interference Evaluation Between Manifold and Wet Christmas Tree CP Systems, 5-28

Pitting Corrosion on Weld Joints of Offshore Structure Jackets, 4-70

Recent Advances in Offshore Cathodic Protection Monitoring, 6-24

Sealer Coatings for Thermal Spray Aluminum in the Offshore Industry, 1-46

OIL AND GAS PRODUCTION

An Improved Corrosion Inspection and Monitoring Instrument for Used Oil Well Tubing, 2-72

Case Study: CP Retrofits on Onshore Facilities, 2-34

Corrosion of API 5L B and X52 in Crude Oil/Water/Gas Mixtures, 2-76

Galvanic Protection of an Offshore Loading Pipeline in the Baltic Sea, 5-24

Interference Evaluation Between Manifold and Wet Christmas Tree CP Systems, 5-28

Repassivation of 13% Cr Steel Dependent on Brine pH, 2-64

Selecting Internal Coatings for Sweet Oil Well Tubing Service, 2-54

PAINT

See **COATINGS**

PIPELINES

Advances in Field Joint Coatings for Underground Pipelines, 8-40

Alpine Pipeline Brings Technology 'First' to Alaska's North Slope, 2-16

Cathodic Protection Criteria and Its Application to Mature Pipelines, 4-26

Complying with the OQ Rule, 2-23

Connector Technologies for Joining Lined Pipeline Segments, 9-48

CORROSION/2000 Plenary Lecture: The Pipeline OQ Rule—Perspectives, Options, and Implementation, 4-18

Corrosion Detection System for Thermally Insulated Pipeline Buried in Soil, 7-72

Corrosion Inhibitor Selection for Arctic and Subsea High-Velocity Flowlines, 3-70

Corrosion Inside Casing—A Field Case History, 12-28

Evaluating Pipeline 'Tape' Coatings—How Do They Compare? 1-43

Fast-Cure AHC Epoxy Coatings for Tank and Pipe Applications, 6-32

Failure Avoidance: MIC Causes Pipe Weld Joint Problems, 6-68

Galvanic Protection of an Offshore Loading Pipeline in the Baltic Sea, 5-24

Management of the U.S. Pipeline Safety Program, 7-20

Northstar Pipeline Designed for Safety in Alaska's Arctic Ocean, 8-20

Selecting Liquid Coatings for Pipeline Repair and Rehabilitation, 8-46

Special Report: SOHIC Without H₂S, 3-86

Summary Report: Fusion-Bonded Epoxy Coatings for Underground Pipelines, 6-38

PITTING ATTACK

See **LOCALIZED CORROSION ATTACK**

POWER PLANTS

See also **BOILERS; HEAT EXCHANGERS**

Coatings for Aboveground Steel in Coal-Fired Plants, 10-36

Current Water Treatment Practices—Utility and Industrial Steam Systems, 10-48

Online Control of Coordinated Phosphate Programs in High-Pressure Steam Generators, 3-76

Steam Surface Condenser Tubes: Watch Out for Sneaky Corrosion, 5-60

Thermal Spray Applications for Power Plant Components, 3-60

REBAR

See **CONCRETE**

REFINERIES

See also **OIL AND GAS PRODUCTION**

Case History: Grooving Failure of Tall Oil Evaporator, 12-70

Cavitation Corrosion in a Continuous Catalytic Reformer Unit, 6-62

Special Report: Caustic Injection Revisited—An Old Method for Controlling Crude Tower Overhead Corrosion, 8-70

Special Report: Refinery Boiler Feedwater Systems: Corrosion and Control, 6-46

SEAWATER

See also **OFFSHORE STRUCTURES**

Case History: Long-Term Evaluation of CP for Interlocking Sheet Pile Bulkheads, 3-38

Corrosion Inhibitor Selection for Arctic and Subsea High-Velocity Flowlines, 3-70

Galvanic Protection of an Offshore Loading Pipeline in the Baltic Sea, 5-24

Interference Evaluation Between Manifold and Wet Christmas Tree CP Systems, 5-28

Pitting Corrosion on Weld Joints of Offshore Structure Jackets, 4-70

Recent Advances in Offshore Cathodic Protection Monitoring, 6-24

STEELS, CARBON

Anodic Protection in the Sulfuric Acid Industry, 12-22

STEELS, STAINLESS

ASTM A 312—Quality? Who Bears the Burden?, 5-70

Case History: Ambient Temperature SCC of Stainless Steel High-Pressure Hose Connectors, 3-96

Case History: Corrosion Failure of Duplex Stainless Steel Equipment in a PVC Plant, 5-76

Special Report: Chloride SCC of Stainless Steel? No—Cyclic Strain Cracking!, 9-78

STRESS CORROSION CRACKING

Case History: Ambient Temperature SCC of Stainless Steel High-Pressure Hose Connectors, 3-96

Phorgotten Phenomena: Condenser Tube Repairs Using Tube Inserts, 5-74

Special Report: Chloride SCC of Stainless Steel? No—Cyclic Strain Cracking!, 9-78

Special Report: SOHIC Without H₂S, 3-86

TANKS

Anodic Protection in the Sulfuric Acid Industry, 12-22

Failure Avoidance: Blistering of Epoxy Lining in Potable Water Tank, 12-44

Fast-Cure AHC Epoxy Coatings for Tank and Pipe Applications, 6-32

Nitrogen Sparging and Blanketing of Water Storage Tanks, 4-56

TITANIUM AND ALLOYS

Failure Avoidance: Handle Titanium in Chlorine Environment with Care, 10-62

Technical Note: Comparison of American and Russian Commercially Pure Titanium, 4-74

WATER, COOLING

Control of Water Treatment Programs in Buildings: Owner and Chemical Vendor Responsibilities, 7-52

Effective Water Treatment of Building HVAC Systems, 5-58

Effect of Cooling Water Impurities on Deposit Control Polymer Performance, 5-54

Reduction of Dissolved Oxygen in Water: Hydrazine and Its Organic Substitutes, 7-58

WELDS AND WELDMENTS

ASTM A 312—Quality? Who Bears the Burden? 5-70

Failure Avoidance: MIC Causes Pipe Weld Joint Problems, 6-68

Pitting Corrosion on Weld Joints of Offshore Structure Jackets, 4-70

ZINC AND ALLOYS

Inorganic Zinc Coatings—Well Known, Yet Commonly Forgotten Facts, 5-38

Phorgotten Phenomena: Maximizing IOZ's Effectiveness with a Three-Coat System, 5-42

Thermal Spray Applications for Power Plant Components, 3-60

Zinc Mesh Cathodic Protection Systems, 8-28

2000 MP Index

Author Index

Abbas, M., 10-62
Abou Shadey, T.H., 2-34
Adey, R.A., 1-28
Ahluwalia, H., 5-70
Ahmad, Z., 8-74
Al-Beed, A., 4-78, 10-62
Al Gami, M.A., 4-78
Allebach, C.L., 9-32
Amjad, Z., 5-54
Amos, G.A., 10-39
Andriés, V., 7-58
Anto, P.F., 4-70
Ashiru, O.A., 10-62
Asrar, N., 10-62
Attard, M., 8-58, 10-58
Avery, R., 1-46
Avila, Y.S., 12-54

Baboian, R., 1-68
Baptista, W., 5-28
Barbin, D., 2-54
Baria, A., 10-22
Bazzoni, B., 9-26
Betts, B.A., 8-78
Birembaut, Y., 4-64
Bossie, E., 3-54
Bouzid, A., 4-64
Brasil, S.L.D.C., 5-28
Brinkley, III, D.W., 6-68
Britton, J.N., 6-24
Broomfield, J.P., 1-64, 7-66
Buecker, B., 5-60
Bunner, M., 1-38
Byrnes, G.B., 3-56

Carpentiers, P., 3-34
Castillo, M., 12-54
Cederquist, S.C., 2-16; 2-23, 3-20, 6-20, 7-18, 7-20, 8-20
Cheng, S., 9-42
Corbett, R.A., 7-77
Cotton, I.J., 6-46, 9-58
Couturier, D., 7-58
Crolet, J-L., 3-86
Cunningham, T., 1-46
Curtin, T.J., 1-28

Dacres, C.M., 2-46
Da Silva, L.P., 10-22
Datta, V.J., 6-32
Davies, K., 7-66
Davies, M., 5-76, 12-70
Davis, G.D., 2-46
Davis, J., 5-44
Davis, J.G., 3-38
Davis, P.E., 9-64
de Abreu, Y., 2-76
Dean, S.W., 9-78
Demoz, A., 8-58, 10-58
Derenne, M., 4-64
de Veer, H., 2-76
Didas, J., 4-26, 6-38
Dillingham, B., 6-32
Donini, J.C., 8-58, 10-58
Dorton, M.R., 9-64
Dougherty, J.A., 3-70
Duan, H., 9-42

El-Raghy, S.M., 2-34
Evans, T.W., 9-64

Fassina, P., 9-26
Feldman, B., 6-62
Filho, F.M., 10-22
Fitzgerald, III, J.F., 4-30
Freedman, A.J., 9-58

Garrett, R., 6-32
Geary, R.W., 1-43
Ghazal, H.H., 2-34
Gibson, G.T., 6-24
González, J.J., 2-76
Greenwood, C., 12-16
Gregoor, R., 3-34
Groves, S., 9-48
Groysman, A., 6-62
Gummow, R.A., 2-26
Gutzeit, J., 8-70

Hawn, D., 9-48
Hays, G.F., 6-52
Hebdon, S.A., 8-78
Herrmann, F., 12-70
Hladky, K., 7-66
Hoffmann, R.A., 9-58
Hollander, O., 3-76, 3-92
Holtsbaum, W.B., 7-26
Hongfang, L., 4-52

Jacobson, G.A., 1-22, 3-30, 9-20
Jiashen, Z., 4-52
Jin, J.H., 2-72
Jing, L., 4-52
Johnson, J.R., 4-42
Jonas, O., 4-56, 10-48

Kain, R.M., 3-96
Kang, M.-C., 7-72
Kang, Y.H., 2-72
Kaufman, A., 6-62
Kim, J.-G., 7-72
Klechka, E.W., 8-46
Knudsen, J.G., 6-52
Koheil, M.M., 2-34
Kohler, K., 5-70
Kranz, M., 12-70
Krebs, L.A., 2-46

La Fontaine, J.P., 6-24
Lazzari, L., 9-26
Lee, J.G., 9-84
Leng, D.L., 8-28
Lewis, B., 4-18
Lewis, R.E., 2-54
Lichtenstein, J., 2-52, 5-42, 7-45, 10-36
Liming, X., 4-52
Lin, W., 9-42
Littleton, J.H., 1-16
Loper, E., 5-60
Lunde, L., 4-74

Mameri, N., 4-64
Man, Y., 6-62
Manian, L., 5-24

Marchand, L., 4-64
Michaelian, K.H., 8-58, 10-58
Mills, G.D., 3-50
Miocque, A., 10-22
Moccari, A.A., 6-68
Mohamed, S.Y., 2-34
Moore, D.P., 4-44
Moosavi, A.N., 8-40
Moriber, N., 3-42, 7-32
Munro, J.I., 12-22

Negrey, R.P., 4-38
Neville, A., 12-64
Nordvik, H.B., 4-74

O'Donoghue, M., 6-32

Palacios, C.A., 12-34
Papavinasam, S., 8-58, 10-58
Perdomo, J.J., 2-76
Pinney, S.G., 7-40
Piron, D.L., 4-64
Potgieter, G., 5-76
Pourbaix, A., 3-34

Revie, R.W., 8-58, 10-58
Reyes, M., 12-64
Rodriguez, Rafael E., 12-34
Rodriguez, Rui E., 12-54
Rudas, M., 1-28

Sadek, A.A., 8-82
Saleh, A.O., 8-62
Sampson, E.R., 3-60
Santon, J., 3-26, 5-20, 9-22
Schmitt, G., 8-62
Scott, P.J.B., 1-54
Seiersten, M.E., 4-74
Selby, K.A., 7-52
Shim, W.W., 12-22
Sia, V., 9-26
Skogsberg, J.W., 2-64
Smart, J., 12-28
Sun, H., 8-58
Swanson, E., 6-32

Tallman, P.M., 5-74

Viloria, A., 2-76, 12-54
Vincent, L.D., 5-38, 10-32

Waguespack, S.R., 12-28
Walker, M.L., 2-64
Wang, S., 9-42
Weldon, D.G., 12-44

Xu, H., 12-64

Yang, S.Z., 2-72
Young, W.T., 9-32

Zhang, J., 9-42
Zibrida, J.F., 5-54
Zuhl, R.W., 5-54

